

(continued CH 604 s/n 5500)

MAIN CABIN/CONFIGURATION:

9 Passenger Fireblocked Interior; Six (6) Leather (natural color) Executive Club Chairs; Pull-out Footrests on Forward Facing Chairs; One (1) 4-Place Divan; Covered in a Natural Color Rayon, Cotton, and Linen Fabric; Ivory Color Headliner and Side Panels; 24K Gold Plated Hardware; Two (2) Divan End Cabinets; All Cabinetry is a Medium Oak Color Finish, Manual Accordion Window Shades; Additional Side Ledge Storage; LH Mid-Cabin Cabinet; Custom Carpet; Chair Electric Lumbar 4-Way (LH and RH #2); Chair Electric Leg rests (LH and RH #2); Widened Seat Armrests; Divan to Berthing Divan. Three Additional Cabin Windows.

ENTERTAINMENT SYSTEM:

Delta Airshow 400 to Airshow Network
(2) 21" Baker Flat screen Monitors
Delta CD Changer with 12 Disk Remote Unit
(2) DVD Players
Outlet and Game Port @ LH #3

EXTERIOR: *New October 2011*

Overall White with Red and Burgundy stripes.

MAINTENANCE

Below Complied with July 2011

- 100, 400, 800, 1600 & 3200 Hour Inspections
- 6, 12, 24 Month Inspections
- SB604-28-017 Upgrade of Fuel Computer to -17 Complied with
- 91.411 and 91.413 Pitot Static and Transponder RVSM Checks Complied with

INFORMATION HEREIN DEEMED RELIABLE BUT NOT GUARANTEED. SPECIFICATIONS SUBJECT TO VERIFICATION UPON INSPECTION. AIRCRAFT IS SUBJECT TO PRIOR SALE OR WITHDRAWAL FROM THE MARKET.